


## 1

Opening the SAS cage option box, you will find these parts:

- Metal cage with sas backplane
- SAS B/P peering cable
- B/P Management cable
- Sata to SAS cable




## 2

Look at the rear part of the SAS backplane and check the jumper (792D\_ID1). It must be positioned in 2-3 pins.



## 3

Insert the cage in the second slot and then connect the peering cable to the J4 connector as shown in the picture. The white cable must be on the white pin. Please connect the other end of the cable to the same connector on the 1<sup>st</sup> cage taking care of the color cable position. The cable must be connected in the same way on both ends.



## 4

**Note:**

The B/P Management cable is necessary only if you are installing the 1<sup>st</sup> sas cage in the system

